# Oil Field Environmental Incident Summary

Incident: 20140610134054 Date/Time of Notice: 06/10/2014 13:40 Responsible Party: ENDURO OPERATING, LLC ENDURO OPERATING, LLC Well Operator: Well Name: NSCU Q-712-H1 Field Name: NEWBURG Well File #: 27785 Date Incident: 6/3/2014 Time Incident: 15:00 Facility ID Number: **BOTTINEAU Sec:** 15 **Qtr:** County: **Twp:** 161 **Rna**: 79 Location Description: Newly drilled well with Matting boards Submitted By: Bryan Pease Received By: Bryan Pease Contact Person: 777 MAIN STREET SUITE 800 FORT WORTH, TX 76102 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil 1 Mile **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Other Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Spilled Units Recovered Units **Followup Units** Oil 3 **Barrels** 3 **Barrels Brine** Other **Description of Other Released Contaminant:** While tripping pump in the new well oil came out the casing. Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: NONE Areal Extent:

# Potential Environmental Impacts:

NONE

# Action Taken or Planned:

Scraped up contaminated soil and loaded in a truck. The amount that was spilled was not noticed until we started taking the matting boards off location (6/9/2014) Future plan is to have truck on casing while tripping in with the pump.

Wastes Disposal Location: Prairie Disposal.

Agencies Involved:

#### **Updates**

Date: 6/10/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

# Notes:

Release, due to an unspecified cause, remained on location within the diking, according to the report. NDIC retains oversight.